

### HEAD OFFICE



1 Genting Link

#02-04, Perfect One

Singapore 349518



(+65) 6748 2277



(+65) 6744 0033



sales@hakko.com.sg




@hakkoproducts

### *How to use Shape H and examples*


This shape differs from Shape J by cutting the tip end. It is suitable for drag soldering and correction of bridging.

\* Not available for correcting bridging by standing the tip end like Shape J.

\* Two kinds of Shape H are available.




900M-T-H




900M-T-1.8H

## Drag Soldering



Put the pad section to the leads and drag the tip along slowly


## Correcting Bridging



“If the bridge amount is small”

Lay down the pad section and drag the tip slowly.

*\*Please operate with clean tip*



“If the bridge amount is large”

Lay down the pad section and drag the tip slowly.

*\*Please operate with clean tip*